


## A guide to using a 4pin - Medium base convertor

(make sure all power is off before starting)


### Step 1:

Cut all the wires going to the lamps



### Step 2:

With all of the ballast wires cut directly wire the 2 power wires to the lampholder. And individually cap the 2 unused wires.



\*make sure to select 1 wire from each side of the lampholder they must be opposite of each other.