



MORRIS CAT#: 23071-23476

Screw-On Wire Connectors



Features:

- Fixed Precise Conical Wire Spring
- No Pre-Twisting of Conductors is Required – Spring Creates its Own Thread
- Reusable Screw on Wire Connector Threads On or Off splice for fast and easy circuit changes and additions
- Tough, UL 94V-2 Flame Retardant Shell will not crack or break, even when applied to maximum wire combinations under extreme pressure
- Ribbed-Cap Provides a more Secure Grip and faster fingertip starts even when hands become slippery
- Deep Skirt Wire Entry Provides Protection from Flash-Over and Shorts
- Threaded Funnel Entry Guides Wire Into Connector Cleanly without Strand Splaying
- Temperature Rated at 221°F (105°C) maximum
- Six Color-Coded Screw On Wire Connectors cover a full range of wire sizes from 22 through 8 Awg



MORRIS CAT#: 23071-23476

Screw-On Wire Connectors



DIMENSIONS - INCHES

CAT. NO.	TYPE	COLOR	WIRE COMBINATIONS	MAX VOLTS	A	B	C	D	E	BOX/BAG QTY	CASE QTY
HANGING BAG 25 PACK											
23271	P1	GRAY	MAX: 3 #20 & 2 #22 MIN: 1 #20 & 1 #22	300V	.150	.264	.339	.228	.598	25	1,250
23272	P2	BLUE	MAX: 3 #18 & 2 #20 MIN: 3 #22	300V	.161	.276	.386	.232	.693	25	1,250
23273	P3	ORANGE	MAX: 4 #16 & 1 #20 MIN: 1 #18 & 1 #22	600V	.197	.390	.480	.307	.862	25	1,250
23274	P4	YELLOW	MAX: 1 #18 & 4 #14 MIN: 1 #18 & 1 #14	600V	.236	.441	.551	.311	.937	25	1,250
23276	P6	RED	MAX: 3 #14 & 4 #16 MIN: 1 #10 & 1 #20	600V 1000V FIXTURES & SIGNS	.276	.504	.630	.350	1.047	25	1,250
BOXED 100 PACK											
23071	P1	GRAY	MAX: 1 #14 & 1 #20 MIN: 2 #22	300V	.150	.264	.339	.228	.598	100	15,000
23072	P2	BLUE	MAX: 3 #16 MIN: 2 #22	300V	.161	.276	.386	.232	.693	100	15,000
23073	P3	ORANGE	MAX: 4 #16 & 1 #20 MIN: 1 #18 & 1 #22	600V	.197	.390	.480	.307	.862	100	10,000
23074	P4	YELLOW	MAX: 1 #18 & 4 #14 MIN: 1 #18 & 1 #14	600V	.236	.441	.551	.311	.937	100	6,000
23076	P6	RED	MAX: 3 #14 & 4 #16 MIN: 1 #10 & 1 #20	600V 1000V FIXTURES & SIGNS	.276	.504	.630	.350	1.047	100	3,600
BAGGED BULK PACK											
23171	P1	GRAY	MAX: 1 #14 & 1 #20 MIN: 2 #22	300V	.150	.264	.339	.228	.598	1,000	20,000
23172	P2	BLUE	MAX: 3 #16 MIN: 2 #22	300V	.161	.276	.386	.232	.693	1,000	10,000
23173	P3	ORANGE	MAX: 4 #16 & 1 #20 MIN: 1 #18 & 1 #22	600V	.197	.390	.480	.307	.862	500	10,000
23174	P4	YELLOW	MAX: 1 #18 & 2 #14 & 1 #16 MIN: 3 #20	600V	.236	.441	.551	.311	.937	500	5,000
23176	P6	RED	MAX: 3 #10 MIN: 3 #18	600V 1000V FIXTURES & SIGNS	.276	.504	.630	.350	1.047	500	5,000
BULK PAIL											
NEW 23179	P1	GRAY	MAX: 1 #14 & 1 #20 MIN: 2 #22	300V	.150	.264	.339	.228	.598	-	13,700
NEW 23180	P2	BLUE	MAX: 3 #16 MIN: 2 #22	300V	.161	.276	.386	.232	.693	-	8,600
NEW 23181	P3	ORANGE	MAX: 4 #16 & 1 #20 MIN: 1 #18 & 1 #22	600V	.197	.390	.480	.307	.862	-	7,200
NEW 23182	P4	YELLOW	MAX: 1 #18 & 2 #14 & 1 #16 MIN: 3 #20	600V	.236	.441	.551	.311	.937	-	4,300
NEW 23183	P6	RED	MAX: 3 #10 MIN: 3 #18	600V 1000V FIXTURES & SIGNS	.276	.504	.630	.350	1.047	-	2,800
SMALL JAR											
23373	P3	ORANGE	MAX: 4 #16 & 1 #20 MIN: 1 #18 & 1 #22	600V	.197	.390	.480	.307	.862	350	11,200
23374	P4	YELLOW	MAX: 1 #18 & 4 #14 MIN: 1 #18 & 1 #14	600V	.236	.441	.551	.311	.937	250	8,000
23376	P6	RED	MAX: 3 #14 & 4 #16 MIN: 1 #10 & 1 #20	600V 1000V FIXTURES & SIGNS	.276	.504	.630	.350	1.047	150	4,800
LARGE JAR											
23473	P3	ORANGE	MAX: 4 #16 & 1 #20 MIN: 1 #18 & 1 #22	600V	.197	.390	.480	.307	.862	900	10,800
23474	P4	YELLOW	MAX: 1 #18 & 4 #14 MIN: 1 #18 & 1 #14	600V	.236	.441	.551	.311	.937	600	7,200
23476	P6	RED	MAX: 3 #14 & 4 #16 MIN: 1 #10 & 1 #20	600V 1000V FIXTURES & SIGNS	.276	.504	.630	.350	1.047	400	4,800

